

Technische Information

Technical Information

02/2018

911 GT3 Cup (991)



ABS - Entlüftungsstück auf Dichtheit prüfen

ABS – Inspection of Blanking Plug Seal

Fahrzeug / Vehicle:	911 GT3 Cup (991 II)
Bauteil / Part:	Verteilungsstück HBZ / Distributor Piece BMC
Modell / Model	2018

Porsche Motorsport empfiehlt vor dem nächsten Betrieb des genannten Fahrzeuges (ausgestattet mit dem ABS Kit von Manthey – Racing), das Entlüftungsstück am Hauptbremszylinder der hinteren Achse (Fahrtrichtung links) auf Dichtheit zu prüfen. Das betroffene Entlüftungsstück, das am Verteilungsstück des Hauptbremszylinders (HBZ) angebracht wird, ist unten in den Bildern rot eingekreist. Eine Undichtigkeit jeglicher Art ist unverzüglich bei Manthey – Racing an aftersales@manthey-racing.de zu melden.

Entlüftungstück / *Blanking plug*



Porsche Motorsport recommends inspecting the blanking plug for leaks on any of the aforementioned vehicles equipped with an ABS kit from Manthey – Racing before the next operation. The blanking plug is attached to the brake master cylinder (BMC) for the rear axle (left in the direction of travel), and is shown circled in red in the images below. Any form of leaks or poor sealing is to be promptly addressed to Manthey Racing at aftersales@manthey-racing.de.

Entlüftungstück / Blanking plug

